

issues

## SERVICE INSTRUCTION no. 2012/4 – revision 1

### Reduction of condensate water at Ignis burner

- With reference to:** Burner units of serial numbers from 598
- Reason:** Operation of Ignis burner using pure propane pressurised close to maximum pressure can cause increased generation of condensate water
- Solution:** Propane flow through coil to be reduced using 1 – 6 blind jets instead of standard jets supplied with the burner. Replacing of 3 jets marked on fig 1 is a preferred option.


#### Repair procedure:

1. Unscrew the jet(s) using wrench key, size 6 (Fig 1)
2. Replace the jet(s) with the blind jet (part no. 54255.00; Fig 2)
3. Fix the blind jet thread using Loctite 620 (part no. 3122.00)

Technical content of this document is approved under the authority of DOA No. EASA.21J.277.

For KUBÍČEK BALLOONS

Petr Kubíček, technical director



Datum: **04 October 2013**




Fig 1 – Jets to be replaced



Fig 2 – Blind Jet to be mouted in