

## Issues

### SERVICE BULLETIN No. BB/31

- 1. WITH REFERENCE TO:** All of the hot-air balloons manufactured by Kubicek spol. s r.o. and BALÓNY KUBÍČEK spol. s r.o.
- 2. REASON:** MTOW change of all balloon models  
Flight manual change No. 11
- 3. REQUIRED ACTION:** By all models of BB type family was changed (increased) MTOW. New values are valid for all new and before now produced balloons, by which was not this value restricted for whatever reason in former times.  
For possibility usage to operate balloon according to new MTOW is necessary to upgrade the Flight manual of concrete balloon with change No. 11.
- 4. DEADLINE FOR ACTION:** Before the first flight, by which will take use of the possibility to load balloon according to new values of MTOW.
- 5. ACTION CARRIED OUT:**  
- By new produced balloons manufactured by BALÓNY KUBÍČEK spol. s r.o.  
- By balloons in operation the operator.
- 6. INDUCED COST COVERED:** By balloons in operation the operator (completion of the missing changes range in existing Flight manual up to No. 11 or new Flight manual).
- 7. NECESSARY MATERIAL:** none
- 8. PROCESS:** Changing the Flight manual up to the last valid change No. 11.  
  
By balloons, what are in operation already, it is not obligatory to using the new MTOW values. The balloon can stay in current mode according to the valid Flight manual for concrete serial number.
- 9. BULLETIN TAKES EFFECT:** 1.8.2007
- 10. ENCLOSURES:**

Technical content of this document is approved on the basis of Approval DOA No. EASA.21J.277.

On behalf of BALÓNY KUBÍČEK spol. s r.o.

Jiří Fuxa

Date: 30.7.2007

