

Issues

SERVICE BULLETIN No. BB/33

- 1. WITH REFERENCE TO:** Hot-air balloons manufactured by BALÓNY KUBÍČEK spol. s r.o. equipped with Ignis burners units of these serial numbers: 387 to 393, 401, 402, 413, 414, 415, 431, 432, 437, 438, 443 – 466, 471 - 476.
- 2. REASON:** Modifications of some parts of above mentioned Ignis burner units (type design changes No. 219BB, 238BB and 239BB approved under the authority of DOA, No. EASA.21J.277)
- 3. REQUIRED ACTION:** Insert a relevant Maintenance Manual Supplement into the Maintenance Manual
- 4. DEADLINE FOR ACTION:** Immediately after receiving this bulletin
- 5. ACTION CARRIED OUT BY:** Owner / operator
- 6. INDUCED COST COVERED:** None
- 7. NECESSARY MATERIAL:** Maintenance Manual Supplement : Ignis 08
(document no. B.0202-IGNIS 08)
- 8. PROCESS:** Print the enclosed file (if delivered by email) or take it as a paper copy when delivered by regular mail, insert it into the Maintenance Manual and note relevant dates into the List of Supplements in para 8.2 of the Maintenance Manual.
- 9. BULLETIN TAKES EFFECT:** 29. Sept. 2008
- 10. ENCLOSURES:** Maintenance Manual Supplement: Ignis 08
(document no. B.0202 IGNIS 08)

Technical content of this document is approved on the basis of Approval DOA No. EASA.21J.277.

On behalf of BALÓNY KUBÍČEK spol. s r.o.

Petr Kubíček

Date: 29. Sept. 2008

