

Issues

SERVICE BULLETIN No. BB/34

- 1. WITH REFERENCE TO:** Hot-air balloons of BB and BB-S types of serial numbers 640 and higher.
- 2. REASON:** New rearranged edition of the Flight Manual and the Maintenance Manual including change of wind speed limitation for take-off by using the quick release mechanism applicable on the BB60 and BB70 models. For combinations of new envelopes with older burners and burner frames the Flight Manual Supplement (*document no. B.2102-0BBF*) apply.
- The general loading graph and loading table is introduced to determine disposable lift according to ambient temperature and altitude instead of previous tables.
- 3. REQUIRED ACTION:** Replace the Flight Manual and Maintenance Manual with the new ones. Familiarize yourself with the structure and content of the new manuals.
- 4. DEADLINE FOR ACTION:** Immediately after receiving this bulletin
- 5. ACTION CARRIED OUT BY:** Owner / operator
- 6. INDUCED COST COVERED:** None
- 7. NECESSARY MATERIAL:**
- Flight Manual (*document no. B.2102*)
 - Flight Manual Supplement Older Burners and Burner Frames (*document no. B.2102-0BBF*) (if applicable)
 - Maintenance Manual (*document no. B.2202*)
- 8. PROCESS:** Print the respective files (if delivered by email or downloaded from Kubicek Balloons website) or take it as a paper copy when delivered by regular mail, and replace the manuals originally supplied by the new edition.
- 9. BULLETIN TAKES EFFECT:** 02. March 2009
- 10. ENCLOSURES:**
- Flight Manual (*document no. B.2102*)
 - Flight Manual Supplement Older Burners and Burner Frames (*document no. B.2102-0BBF*)
 - Maintenance Manual (*document no. B.2202*)

Technical content of this document is approved under the authority of DOA No. EASA.21J.277.

On behalf of BALÓNY KUBÍČEK spol. s r.o.

Petr Kubíček

Date: 02. March 2009

