

issues

## MANDATORY BULLETIN No. BB/18a

- 1. WITH REFERENCE TO:**
- 1) All of the hot air balloons manufactured by 114 (714) ZO Svazarmu, Aerotechnik, Aerotechnik p.o.s. and Aerotechnik s.r.o.
  - 2) All of the hot air balloons manufactured by Kubíček spol. s r.o. and BALÓNY KUBÍČEK spol. s r.o.
- 2. REASON:**
- 1) Extension of the BB type with the new BB30Z envelope and the K25P basket
  - 2) Change of the inspection validity of Schroeder fuel cylinders
  - 3) Change of the time limit concerning ball cocks of liquid and vapour phases
- 3. REQUIRED ACTION:** Change of the relevant sheets of the Maintenance Manual concerning all translations
- 4. DEADLINE FOR ACTION:** Immediately after this bulletin receiving
- 5. ACTION CARRIED OUT:** Balloon operator
- 6. INDUCED COST COVERED:** None
- 7. NECESSARY MATERIAL:** None
- 8. PROCESS:**
- 1) Cancel the relevant sheets of the present Maintenance Manual
  - 2) Insert the new ones (Change 1, Issue 19.12.2001)
- 9. BULLETIN TAKES EFFECT:** From the date of the CAA, Czech Republic approval.
- 10. ENCLOSURES:** Sheets: (i)/(ii)  
2-7/8  
3-7/8, 3-9/10  
4-3/4  
6-21/ILB

*On behalf of the manufacturer:*

*Ing. Josef Pučégl*

*Date: 15.1.2002*

